



Conductivity Results Map



<p>CLIENT:</p>	<p>FIELD NOTES:</p> <ol style="list-style-type: none"> 1. CONDUCTIVITY SURVEY COMPLETED BY GEOSCAN SUBSURFACE SURVEYS IN SEPTEMBER 2018. CHANGES TO THE SITE THAT OCCURRED FOLLOWING OUR INVESTIGATION WILL NOT BE SHOWN. 2. THE SURVEY WAS PERFORMED USING ELECTROMAGNETIC (EM) CONDUCTIVITY EQUIPMENT. 3. PLEASE REFER TO THE WRITTEN REPORT FOR METHODS, RESULTS, RECOMMENDATIONS AND LIMITATIONS DISCLAIMER 	<p>DISCLAIMER:</p>	<p>PROJECTION:</p> <p>UTM</p>	<p>DATE:</p> <p>SEPTEMBER, 2018</p>
			<p>SITE ADDRESS:</p> <p>VANCOUVER ISLAND, BC</p>	<p>CREATED BY:</p>
			<p>JOB ID:</p>	<p>SURVEYED BY:</p>

